

	2.0.000		5-5-55				
	CHECKED	NRS	4-8-99		$\dot{\mathbf{a}}$		
MATERIAL	APPD	MJC	4-8-99		CI	RC	COR
PROCESS	METHODS						
UNLESS OTHERWISE SPECIFIED ASME Y14.5M-1994. COMMENTS: SUCTION STRAINER AND DISCHARGE RELIEF VALVE MUST BE PROVIDED. ALIGNMENT: UNITS ARE ACCURATELY ALIGNED AT THE FACTORY. ALIGNMENT SHOULD BE CHECKED BEFORE STARTING TO ENSURE THAT IT IS STILL WITHIN .005				TITLE			STANDARI 5A[143/
ID 131 FIM. PRESTARTING: FLUSH SUCTION PIPING BEFORE CONNECTING PUMP. PRIME AND VENT PUMP. READ INSTRUCTION MANUAL FOR DETAILS BEFORE STARTING.			first order E1102A	SIZE	cage code 59180	DWG N	sdd
	USED ON			SCALE	1/2	WEIGHT	SEE NOTE 5
							4

1			
date -11-24	<sub>вү</sub> CDG	approved JEC	
-11-24	CDG		
			F
			E
			D
			С
			<u> </u>
	(16)		
			D
			D
	]		
IM	O®		Α
 RD (STE	- •		
/162]_	_		
D1964	5   OF		
5 SHEET			